

----- Forwarded message -----

From: **Randy Taylor** <randy.taylor@hok.com>

Date: Tue, Aug 21, 2018, 6:17 PM

Subject: FW: RFIs - Aqua Regia and Teaching Lab

Dear Bidders,

Please see RFI questions and responses below that have been received to date.

See RFI questions below:

1. Aqua Regia drawing MP2.01 note 3 says to replace the existing duct in the lab up to this point. The build back drawings do not indicate this duct to be replaced, it is not shown in dark print. A/E please advise if it is to be replaced and if it is please provide size of existing duct. **HOK Response: Existing duct is to be replaced in kind – same size and same location.**
2. Room 280 Teaching Lab renovation sheet M2.01 shows to install a new general exhaust valve. Does the duct associated with GET 2.2.11 need to be welded stainless or can it be galvanized? **HOK Response: Rice's campus standards are to provide stainless steel, welded for all laboratory exhaust. Provide welded stainless steel.**

Sincerely,

RANDY TAYLOR

HOK

randy.taylor@hok.com

t +1 713 407 7872